

AquaTight® EX 11

EX11N716WS



1 Cut the cable squarely.



2 Using a fixed blade prep tool in good condition, prepare cable to 1/4" x 1/4" dimensions.




3 Ensure cable is prepared to 1/4" x 1/4" dimensions.



4 Ensure there is no dielectric, braid or foil wrapped around center conductor. Fold back braid.



5 If tri-shield or quad, remove outer layer of foil.




6 Fold back inner braid.



7 Align center conductor and dielectric with marking grooves on connector body.



8 Mark cable at the base of the connector with thumbnail or other marking device.



9 Insert cable into connector and push firmly while rotating clockwise until the connector reaches the mark on the jacket.



10 Properly seat connector into VT-200 tool and compress.



11 Visually inspect to ensure connector is fully compressed. Tighten to recommended torque.



EX11N716WS

VT-200



Part Number	Description
EX11N716WS	EX AquaTight® Series 11 Compression Connector
VT-200	Universal compression tool, "XL" series body

This product may be protected by one or more patents • For further information, please visit: www.ppc-online.com/patents

customerservice@ppc-online.com • 1-800-800-6652 • www.ppc-online.com